



3/23

FIG. 3A




FIG. 3B




FIG. 3C




FIG. 4




FIG. 5

5/23





FIG. 6






FIG. 7

FIG. 8A




FIG. 8B




FIG. 8C





FIG. 8D



8/23

FIG. 9






FIG. 10




9/23


FIG. 11



10/23

FIG. 12





12/23

FIG. 14A





FIG. 14B








FIG. 15




Improper Placement:
Incomplete Ablation
of Tumor Volume

FIG. 16A



Improper Placement:
Insufficient Healthy
Tissue Margin


FIG. 16B



Proper Placement


FIG. 16C

FIG. 17A



Detection of Incomplete Ablation
via rotation of electrode/sensor array

FIG. 17B



Detection of Incomplete Ablation
Deployment of passive Resilient Members 18
of Sensing Members 22m





FIG. 18A




FIG. 18B




FIG. 18C




FIG. 19




FIG. 20



18/23




FIG. 21A




FIG. 21B




FIG. 21C




FIG. 21D




FIG. 21E




FIG. 21F




FIG. 21G




FIG. 21H

19/23




FIG. 22




FIG. 23




FIG. 24

20/23




FIG. 19




FIG. 20




FIG. 21





FIG. 22






FIG. 30




FIG. 31